

Erratum

Study of aeration efficiency at stepped channels

A. Baylar and M. E. Emiroglu

Further to the publication of this paper in *Proceedings of the Institution of Civil Engineers, Water and Maritime Engineering*, 156, No. 3, 257–263, the following amendments should be made.

On page 262 in equation (5), the constant, 0.262, should be 0.549. The corrected equation should be in the following form:

5

$$E_{20} = 1 - \left[1 + 2.161 (\sin \alpha)^{0.290} 0.549 (y_c/h) \right]^{-1}$$

A rough computation for a step height 0.1 m, slope 1:2.5 and $y_c/l = 0.5$ giving $q = 140 \times 10^{-3} \text{ m}^2/\text{s}$, gives $r_{20} = 1.77$ for equation (5).

The values of the horizontal axis given in Figs 3(a)–(c) and Figs 5(a)–(c) are written incorrectly. The written values given as 0.0, 0.2, 0.4, 0.6, 0.8, 1.0, 1.2, and 1.4 should be 0.0, 0.45, 0.90, 1.35, 1.80, 2.25, 2.70 and 3.15. No correction is required for the slope of the curve.

The correct version of this paper is available on the internet at www.watermanagementjournal.com.